## HOREF EXPERTISE.

## MID-TRIP INSPECTION

OFFER VALID AUG.1-SEPT. 17, 2016


A quick, non-measured inspection of key items the DOT looks for that you may not notice:

- **✓** TIRE TREAD DEPTH
- BRAKE SHOE
  THICKNESS/CONDITION
- MUD FLAPS
- **✓** AIR LEAKS
- **WHEEL SEALS**
- FLUID LEAKS

- **EXHAUST**
- **MIRRORS**
- FIRE EXTINGUISHER
- **TRIANGLES**
- **UIGHTS**
- CONSPICUITY TAPE

Self-adjusting brake adjusters do not eliminate or reduce the need for periodic inspection and maintenance of the adjuster components and attaching hardware. Self-adjusting brake adjusters should never be operated as a manual adjuster, if the self-adjusting function is not operating properly. For your safety, TA and Petro brand locations do not adjust automatic slack adjusters.

**Location Instructions:** Use standard service code **DOMT**. Use payment type **CPN** as the first payment type. For payment number use **DOMT 2016**. Enter dollar value of this coupon (19.99 labor). Customer's new total will appear in second payment type. This is an "at-site" discount.







MORE: BAYS. EXPERTISE. SOLUTIONS.





