HORE EXPERTISE.





JUNE 7-9



ROBERT ANDERSON

2015 TMC SuperTech Station Winner, Brakes

Brakes: #1 reason for out-of-service violations!

MID-TRIP INSPECTION OFFER VALID MAY 1 - JUNE 9, 2016

A quick, non-measured inspection of key items the DOT looks for that you may not notice:

- TIRE TREAD DEPTH
- BRAKE SHOE THICKNESS/CONDITION
- **MUD FLAPS**
- **V**AIR LEAKS
- **WHEEL SEALS**
- **FLUID LEAKS**

- **EXHAUST**
- **MIRRORS**
- FIRE EXTINGUISHER
- **TRIANGLES**
- **LIGHTS**
- **CONSPICUITY TAPE**

Self-adjusting brake adjusters do not eliminate or reduce the need for periodic inspection and maintenance of the adjuster components and attaching hardware. Self-adjusting brake adjusters should never be operated as a manual adjuster, if the self-adjusting function is not operating properly. For your safety, TA and Petro brand locations do not adjust automatic slack adjusters.

Location Instructions: Use standard service code DOMT. Use payment type CPN as the first payment type. For payment number use DOMT 2016. Enter dollar value of this coupon (19.99 labor). Customer's new total will appear in second payment type. This is an "at-site" discount.



MORE: BAYS. EXPERTISE. SOLUTIONS.





